

# WIRE MANAGEMENT

## Self-Adhesive Label

Lockout/Tagout  
VL, DSS Series

**CAUTION:** In Accordance with OSHA Standard 1910.147, All Equipment, Machines and Processes Shall Be Locked Out Prior to Servicing. Lockout Procedures are Posted in the Main Operating Area and/or by the Main Energy Source of Each Machine. If You Have any Questions About the Lockout Procedures, Please See Your Supervisor or the Safety Director. This Standard Will Be Strictly Enforced.

### FEATURES

- Self-adhesive labels are sub-surface printed polyester labels.
- Rigid signs are available in either polycarbonate or polyester material.



CAT. NO.	FIG. NO.	LEGEND	SIZE (IN.)	STD. CTN. QTY.
VL-7	1	Warning Potential Arc-Flash Hazards Exist While Working on this Energized Equipment.	2 1/4 x 4 1/2	25
VL-8	2	Warning Potential Arc-Flash Hazards Exist While Working on this Energized Equipment.	4x6	25
DSS-5	3	High Voltage.	10 x 14	25
DSS-6	4	High Voltage Keep Out.	10 x 14	25